

## PRESS RELEASE

### FATAL ACCIDENT OCCURS AT THE CABANASSES MINE IN SÚRIA, CATALONIA, SPAIN

December 6, 2013

Two mine operators at Iberpotash's Cabanasses mine located in Sùria, Spain, died today in an accident that occurred inside one of the mine's galleries.

The two operators were on the night shift, and together with their co-miners, were engaged in maintenance work on the continuous mining machine when the roof fell in and buried them.

The cause of the accident is unknown at this stage and is under investigation by the company and the relevant authorities.

Management and employees of ICL are terribly saddened by the news of this accident, and express their deepest condolences to the miners' families and colleagues.